




# Assembly Instruction

## Neutrik NC3MXX-HD-B-D



**A** Slide the rubber sealing (1) and the boot (2) onto the cable.

**B** Prepare cable as shown.

**C** Insert wires into the terminals and solder them.

**D** Put chuck onto the cable.  
**Attention: Pay attention to the guiding key.**

**E** Slide insert and chuck together into the housing.

**F** Turning the bushing onto the connector.

► Rubber sealing assembly see on page 2.



# Assembly Instruction

## Neutrik NC3MXX-HD-B-D

**G** Put the assembly tool onto the female connector over the end of the bout (as shown in picture).

**H** Push the rubber sealing onto the assembly aid.  
**Attention: Pay attention to the position of the Push (see the picture).**

**I** Hold the cable and pull the assembly tool jerkily off the connector (the sealing jacket is pulled in position).

► **Finish**

### ASSEMBLY OF MALE CONNECTOR




- A** Repeat the steps
- F**
- G** Push the rubber sealing onto the plug.
- **Finish**

### ORDER OF ASSEMBLY


NC3FXX-HD



Rubber sealing




bushing



chuck



insert



housing

NC3MXX-HD

